


Assembly Instruction Sheet #IS-1246P39 For Style 1246P39

Total Required: Filled enclosure, Philips screwdriver, glue, wire cutters, wire strippers, electrical tape, safety glasses.
Light Sources: 120V LED MAX 1W (20000).
Estimated Assembly Time: 30-40 minutes.
Preparation: Identify and inspect all parts before beginning installation. Check package content list and diagrams before to be sure all parts are present. If any parts are missing or damaged, do not attempt to assemble, install, or operate the fixture. Contact our service center for replacement parts.

⚠ Warnings and Cautions


Turn off electricity at circuit breaker or main fuse box before installation. Consult a licensed electrician if in doubt. These instructions are provided for your safety. It is very important you read them completely before installing the bulbs. We strongly recommend that a licensed, professional electrician perform the installation. Disconnect fixture from power source before replacing bulbs. Make sure bulbs are given sufficient time to cool before removal.

Package Contents



STEP 1 - Release Crossbar from Colling Canopy.

A Fixture Body x1



2 Class X

— 29 —



3 Glass X¹

1

C Ceiling Canopy x1



4 Glass X

10

5 Glass X²

—

6 Glass Xt

Hardware Contents

PART	DESCRIPTION	QUANTITY
BB	Wire nut	2pcs
CC	Screw	2pcs



STEP 3 - Attach Mounting bracket to Outlet Box
A. Pass the supply wires through the Mounting bracket(EE),
Attach the Mounting bracket (EE) to the Outlet Box




Figure 3

STEP 5 - Install Ceiling Canopy to Ceiling




Figure 5

STEP 4 - Wire Connections

connections. Twist connectors until wires are tightly joined together. Wrap each connection with approved electrical tape and carefully stuff all the connected wires into the Outlet Box.





Figure 4

STEP 6 - Install Glass.




Figure 6